

Catalyst Tables

Use hardware package #17715P-3
which contains the following...

8 - 5/16" x 1-1/4" Bolts
8 - Lock Washers

1. Place leg in corner and insert bolts into lock washer and leg as shown.
2. Tighten bolt with 1/2" socket wrench.
DO NOT OVER TIGHTEN.
DO NOT EXCEED 150 in/lb torque.
3. Place table upright and adjust glides as needed to level.

